

NON-FRIABLE ASBESTOS CLEARANCE CERTIFICATE – NO AIR MONITORING

SECTION A – CLEARANCE INSPECTION DETAILS

Client details			
Name of client:	Mr Luca Cossetto		
Client contact details:	[REDACTED]		
Removal work details			
Date removal work carried out:	6 th April 2024		
Site address where removal work is being carried out:	94 Horatio Street, Nudgee NSW 2850		
Details of the specific asbestos removal work area(s):	External Walls		
Name of licensed asbestos removalist:	Rony Zeait		
Name and contact details of licensed asbestos removalist supervisor (if different to removalist):	[REDACTED]		
Inspection details			
Date of clearance inspection:	06/04/2024	Time of clearance inspection:	12pm
ASBESTOS REMOVAL WORK PAPERWORK		Yes	No
Do you have a copy of the asbestos removal control plan?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Do you have a copy of the notification form?		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Is the removal work consistent with the control plan and the notification form? (e.g. use of enclosures, decontamination facilities, waste facilities)		Unknown	<input type="checkbox"/>
ASBESTOS REMOVAL WORK AREA Visual Inspection			
Inspection of the specific area detailed in Section A found no visible asbestos remaining as a result of the asbestos removal work carried out.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Was air monitoring required		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Can the area be reoccupied?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has additional information been attached? (e.g. photos, drawings, plans)		<input type="checkbox"/>	<input checked="" type="checkbox"/>

CLEARANCE DECLARATION

I declare that:

- Inspection found no visible asbestos residue from asbestos removal work in the area, or in the vicinity of the area, where the work was carried out
- The area is safe for reoccupation and normal use

Name:	Eco Demolition NSW P/L Michael Chidiac	Signature:	[REDACTED]
Contact number:	[REDACTED]	ABN:	63 606 596 169
Address:	135 Parramatta Rd, Concord NSW 2137		
Qualification:	Conduct Asbestos Assessment Associated with Removal 1138/2017 License #AD212242		